

Fox Valley Tool & Die, Inc.

Design & Build - Tool & Die - Jig & Fixture - EDM - CNC Machining

Phone: 920-766-9455 Fax: 920-766-9135 Toll Free: 1-888-585-FVTD(3883)

E-mail Address: fvtd@fvtd.com

Website Address: <http://www.fvtd.com>

Cad Data Transfer Information

2D CAD File Import Formats

Creo 2, 3, & 4

.DRW • Native Pro E File
.DXF • DXF File
.IGS • IGES File

SolidWorks 2016 & 2017

.SLDDRW • Native SW File
.DXF • DXF File
.IGS • IGES File

AutoCAD 2016

.DWG • Native AutoCAD File
.DXF • DXF File
.IGS • IGES File

3D CAD File Import Formats

Creo 2, 3, & 4

.PRT • Native Pro E File
.STP • STEP Files (Solid)
.SAT • ACIS Files (Solid)
.IGS • IGES Files (Surfaces)
.NEU • (Not Release Sensitive)

SolidWorks 2016 & 2017

.SLDPRT • Native SW File
.STP, .STEP • STEP File (Solid)
.IGS • IGES File (Solid)
.X_T, .X_B • Parasolid File
(Solid)

Rhino Nurb Surfacing

.3DM • Native Rhinoceros File
.STP • STEP File
.IGS • IGES File
.VGA • VGA File

Secondary manufacture software is available for Pro-E and SolidWorks (Pro-Manufacture & Esprit).

2D Mazatrol Offline Programming

CamLink GB/GeoEntry

.GEO • Native CamLink File
.DXF • DXF File

Transfer Methods

We use WinZip (.ZIP) for file compression (only necessary on sizeable files).

- Email: fvtd@fvtd.com
- Mail: CD & DVD, and flash drives
- FTP Site: <https://files.fvtd.com> (Call for ID & password or log onto our website and request one.)